



NUMBER: 18-078-16

GROUP: Vehicle Performance

DATE: July 20, 2016

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 16-064. ALL APPLICABLE UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE UN-SOLD VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

FOR HELP WITH USING wiTECH FOR ECU FLASH REPROGRAMMING, CLICK ON THE APPLICATION'S "HELP" TAB.

THE wiTECH SOFTWARE IS REQUIRED TO BE AT THE LATEST RELEASE BEFORE PERFORMING THIS PROCEDURE.

SUBJECT:

Engine Oil Viscosity Upgrade And Flash Enhancements

OVERVIEW:

This bulletin involves reprogramming the Powertrain Control Module (PCM) and the Transmission Control Module (TCM). It also involves changing the engine oil with new 5W40 engine oil and applying a sticker to the engine oil filler cap. An addendum card will need to be added in the owner's manual.

MODELS:

2016	(WK)	Jeep Grand Cherokee
2016	(DS)	Ram 1500 Pickup

**NOTE: This bulletin applies to vehicles within the following markets/countries:
NAFTA.**

NOTE: This bulletin applies to vehicles built on or before June 30, 2016 (MMDDHH 0630XX) and equipped with a 3.0L Diesel Engine (Sales Code EXF).

SYMPTOM/CONDITION:

The following powertrain system improvements/enhancements are included in this software release:

- Fan calibration.
- Transmission calibration.
- Revised oil change algorithm.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in TechCONNECT, verify all related systems are functioning as designed. If DTCs are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the vehicles VIN is listed in VIP or your RRT VIN list, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
10 Qts. (DS) and 8 Qts. (WK)	68147411PA (Drum)	SAE 5W-40 Rotella Full Synthetic Engine Oil
10 Qts. (DS) and 8 Qts. (WK)	68001332PA (or equivalent)	SAE 5W-40 Rotella Full Synthetic Engine Oil (Quart)

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the PCM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Clear any DTCs that may have been set in other modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.
3. Reprogram the TCM with the latest software.

CAUTION: Do not clear the shift adaptives in the TCM's memory. This action may cause the transmission to not shift smoothly until the adaptives are re-learned.

4. Clear any DTCs that may have been set in other modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

NOTE: Do not remove oil filter cap or change the oil filter. Replace the engine oil only by following the steps below.

5. Run engine for 10 minutes before oil change to warm up the engine oil.
6. Remove oil fill cap.
7. Clean top of oil fill cap with Isopropyl alcohol or equivalent and apply engine oil viscosity rating sticker as shown in (Fig. 1).

NOTE: Oil filler cap stickers and Owner Manual Addendum cards have been shipped to your dealer, free of charge, to the attention of the Parts Manager and Service Manager.



Fig. 1 Cap Before Sticker Applied

- 1 - Do Not Cover This Embossed International Oil Symbol
- 2 - Cover This Old Oil Info Symbol With The New "5W40" Label

-
8. Remove the oil drain plug and allow oil to drain for at least 5 minutes or until it stops dripping.

9. Inspect the oil drain plug and gasket for damages ([Fig. 2](#)). Replace if necessary.



Fig. 2 Damaged Rubber Seal

1 - Oil Drain Plug Gasket Seal Crushed

-
10. Reinstall the oil drain plug. Tighten to 45 N·m (33 ft. Lbs.).
 11. Add 5W-40 synthetic engine oil to the engine. Use 10 quarts for (DS) Ram trucks and 8 quarts for (WK) Jeep Grand Cherokee. Take care not to spill oil on engine.

12. Replace the oil fill cap with the new 5W-40 sticker firmly attached (Fig. 3).



Fig. 3 Cap After Sticker Applied

1 - "5W-40" Sticker Affixed To Oil Filler Cap

NOTE: Do not reset the oil life message on any new vehicles (under 500 miles).

13. Start engine and run for one minute. Shut the engine off and wait five minutes for oil to drain down to sump. Verify the engine oil level is correct. Oil level must be at "MAX" level +/- 2 mm (Fig. 4).



Fig. 4 Oil Dipstick

14. Insert addendum card into owner's manual.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
09-00-00-90	Reprogram Powertrain and Transmission Control Modules, Change Engine Oil with Fill Cap Sticker and Insert Addendum Card into Glove Box (0 - Introduction)	10 - Diesel	0.9 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 1 minute. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

ZZ	Service Action
----	----------------